


0085-Main.Sch

0085-Power.Sch


Title <b>0085 Opto Isolator (Project)</b>			Ranger Instruments Pty. Ltd.
Size: A4			41 Success St
Number: 0085-100	Revision: 1.1	Acacia Ridge	
Date: 15-Jan-2003 Time: 10:48:13			QLD
Designed By: Opi Taumalolo	Sheet 1 of 3	Australia 4110	
File: 0085-Project.PRJ			Error : Ranger1.bmp file not found.

# 0085 Main




Title: <b>0085 Opto - Isolator (Main)</b>			Ranger Instruments Pty. Ltd. 41 Success St Acacia Ridge QLD Australia 4110	
Size: A4	Number: 0085-100	Revision: 1.1	Error: Ranger1.jpg file not found.	
Date: 15-Jan-2003	Time: 10:48:13	Sheet 2 of 3	File: 0085-Main Sch	
Designed By: Opt Tammalok				

# 0085 Power Supply



\* Fuse not used on 1400 Profibus



Title <b>0085 Opto-Isolator (Power Supply)</b>			Ranger Instruments Pty. Ltd. 41 Success St Acacia Ridge QLD Australia 4110
Size: A4	Number: 0085-100	Revision: 1.1	Error : Ranger1.bmp file not found.
Date: 15-Jan-2003	Time: 10:48:13	Sheet 3 of 3	
Designed By: Opi Taumaloto			File: 0085-Power.Sch